



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
March 16, 2006

Supervisor *DRH*

Mine Name: Apex Mine
Operator Name: Teck Cominco American, Inc.
David W. Godlewski
15918 East Euclid Avenue
Spokane, Washington 99216

Permit number: S/053/004
Inspection Date: February 27, 2006
Time: 4:30 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Inactive

Weather: Sunny, Cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Inspected the site while in the area.

Inspection Summary:
The site does not appear to have changed since my last visit on June 21, 2005.
I parked at the gate and walked into the site. Because there did not appear to any major changes, I did not spend a lot of time at the site. No photos or GPS data was collect during this visit.

Conclusions and Recommendations:
This site remains on the inactive status, I will inspect the site when I am in the area.

Inspector's Signature

Doug Jensen

Date: 3/16/06

dj:pb

cc: Teck Cominco American, Inc.

O:\M053-Washington\M0530004-ApexMine\Inspections\02272006insp.doc